



**COMPLETE  
METALWORKING  
SOLUTIONS**

**(800) 991-4225**

[www.ahbinc.com](http://www.ahbinc.com)

ISO Certified

[customerservice@ahbinc.com](mailto:customerservice@ahbinc.com)

Using GMA lined bulk- proper discharging:

- 1) Line forklift tines through lifting loops



- 2) Open top of bulk bag duffle to expose top of inner liner:



- 3) Cut inner line zip tie and pull upwards towards each lifting loop; pull inner liner under lifting loop:



- 4) Wrap inner liner back over lifting loop tightly then clamp to forklift tine:



- 5) 2<sup>nd</sup> view showing 2<sup>nd</sup> clamp on opposing corner



- 6) Lift bag and open distribution chute (sometimes the drawstring must be cut) pull down distribution chute:



- 7) Slice inner liner cleanly (note; single slice pours reasonably slowly, and a 2<sup>nd</sup> slice can be made perpendicular to increase flow)



- 8) Garnet should flow smoothly and inner liner should not slide into distribution chute:

