



WOW WORKHOLDING

QUICK CHANGE PALLET SYSTEM

Stop struggling to find a way to hold your small parts effectively and efficiently.


With a WOW Workholding Quick Change pallet system put small parts on a pallet and always have the next pallet/part setup and ready. This will allow you to keep your setup in the same spot every time.

Many machine shops struggle with spindle inefficiency. WOW Workholding offers an efficient and predictable setup solution. Our customers are better prepared for their machining processes and as a result have less stress in their manufacturing.

Competition is tough. Do not fall behind. We have a solution.


ADVANTAGES

- Change pallets faster with 1 single screw.
- Load and prepare your next part on another pallet to make for quick change over time
- Maintain 1 setup for a variety of parts
- Quick changing between parts
- Can be used in 3, 4 and 5 axis setups
- Accuracy & Repeatability
- Maximum weight capacity 250 lbs



BASIC QUICK-CHANGE ASSEMBLY

Fasten directly to your table with out the need of a modular base plate. This option is an excellent way to keep costs down yet still benefit from the speed of a quick-change pallet.



QUICK-CHANGE ANGLE BLOCK ASSEMBLY

Use the quick change pallet on our angle block to use for 4th-axis operations with the ability to position or tumble your parts to machine 4 sides. This can be setup on any 3-axis mill giving you excellent flexibility in your scheduling. Also, you will not have to keep it permanently on your machine table, so it will not take up any valuable machine space.

Asks us about custom sizing and configurations to meet your specific needs



**COMPLETE
METALWORKING
SOLUTIONS**

(800) 991-4225

www.ahbinc.com

ISO Certified


customerservice@ahbinc.com



**Proudly made in
NORTH AMERICA**


Rian Solutions is in no way affiliated with any other 'Work Holding Systems' or 'Companies'. Any 'Work Holding Systems' we are offering for sale are manufactured in North America by Rian Solutions exclusively, and not in cooperation with any other company or system.

QUICK CHANGE PALLET SYSTEM




QUICK-CHANGE 4TH AXIS ASSEMBLY

Adaptable to your 4th axis for fast and easy change overs from part to part while reducing your setup time.




QUICK-CHANGE 3-JAW CHUCK ASSEMBLY

A quick-change assembly option for your 3-jaw chuck will allow you to go from a top pallet to a chuck in seconds.



QUICK-CHANGE VISE ASSEMBLY

Use the quick-change system with our modular vise. This will allow you to mount the vise without any indicating. The speed of change over will increase your spindle time. This is an excellent option for 5-axis applications.



QUICK-CHANGE WITH EXTENSION



An excellent option for 5-axis machining of smaller components to allow for a greater ease of reach while still enjoying fast and accurate setups.



300MM DIAMETER QUICK-CHANGE TOP PLATE

Standard pallet tops are 155mm in diameter but the option to go to 300mm in diameter as well as larger screw sizes (M6, M8, M10) to accommodate larger parts for 5-axis machining.

Order your pallets with a blank top face to allow for your own custom fixturing needs.



**COMPLETE
METALWORKING
SOLUTIONS**

(800) 991-4225

www.ahbinc.com

ISO Certified

customerservice@ahbinc.com

