












PART FORMING SEQUENCE ATHENS MODEL ACL-3-12 CONE ROLLING MACHINE













IMG_0304.JPG




IMG_0306.JPG



IMG_1699.JPG



IMG_1702.JPG



IMG_1703.JPG



IMG_1706.JPG




IMG_1707.JPG



IMG_1709.JPG




IMG_1712.JPG



Waldemar CL-16-48

12-07-18





Waldemar CL-16-48

12-07-18



WARNING
CAUTION: LASER RADIATION
DO NOT STARE INTO THE BEAM
DO NOT POINT AT OTHERS
DO NOT TOUCH THE OPTICAL SURFACES
DO NOT TOUCH THE MOVING PARTS
DO NOT TOUCH THE ELECTRICAL PARTS