





## Light and Extra-Light Live Centers


- Accuracy guaranteed to  $\pm .00005$ .
- Light live center designed for 2 to 10 lb. workpiece loads.
- X-Light live center designed for extremely light workpiece loads – 2 oz. to 2 lb.
- Excellent for very small workpieces. Used in medical, orthopedic, aerospace and similar applications.
- Free turning.
- Maximum 8,000 RPM.



Extra-Light Live Center and quarter shown actual size



Maximum axial load: 500 lbs.



Maximum axial load: 100 lbs.

### LIGHT LIVE CENTER - MORSE TAPER

Model	Taper	A	B	C	D	E	Max RPM	W. P. Weight
40552	2	3/8	7/8	11/2	21/16	3/16	8000	10
40553	3	3/8	7/8	11/2	21/16	3/16	8000	10
40554	4	3/8	7/8	11/2	21/16	3/16	8000	10
40555	5	3/8	7/8	11/2	21/16	3/16	8000	10

### EXTRA-LIGHT LIVE CENTER - MORSE TAPER

Model	Taper	A	B	C	D	E	N	Max RPM	W. P. Weight
40101	1	9/32	7/8	11/4	13/4	3/16	3/4	8000	2
40102	2	9/32	7/8	11/4	13/4	3/16	3/4	8000	2
40103	3	9/32	7/8	11/4	13/4	3/16	3/4	8000	2
40104	4	9/32	7/8	11/4	13/4	3/16	3/4	8000	2